



*Larson Systems Inc.*



*Capacitance Free Length Gage  
User Manual*



|  |          |
|--|----------|
| <b>INTRODUCTION.....</b>                         | <b>3</b> |
| <b>SPRING MEASUREMENT BASICS .....</b>           | <b>3</b> |
| CALIBRATION.....                                 | 3        |
| A TYPICAL CALIBRATION CYCLE:.....                | 4        |
| A TYPICAL MEASUREMENT CYCLE .....                | 4        |
| IMPORTANT CONSIDERATIONS .....                   | 5        |
| <i>Sensitivity</i> .....                         | 5        |
| <i>Multiple Sampling</i> .....                   | 5        |
| <i>Thermal Stability</i> .....                   | 5        |
| <i>Zeroing the Output Voltage (Offset)</i> ..... | 5        |
| <i>Zeroing Errors</i> .....                      | 6        |
| <i>Probe Contact Errors</i> .....                | 6        |
| <b>HARDWARE.....</b>                             | <b>7</b> |
| PROBE DRIVER.....                                | 7        |
| CONNECTIONS.....                                 | 8        |
| <b>SOFTWARE .....</b>                            | <b>9</b> |
| LP_INITIALIZE .....                              | 9        |
| LP_SETUP_PROBE.....                              | 9        |
| LP_ZERO_PROBE .....                              | 11       |
| LP_GET_SPRING_LENGTH.....                        | 12       |
| LP_GET_PROBE_VOLTAGE.....                        | 12       |
| LP_VOLTS_OUT .....                               | 13       |
| LP_CONVERT_VOLTS_TO_LENGTH .....                 | 13       |
| LP_FIT_POINTS .....                              | 14       |
| LP_FIND_HORIZONTAL_POINT.....                    | 15       |

## Introduction

The Larson Systems Capacitance Free Length Gage is a self contained probe driver assembly and probe for adding capacitance based spring free-length measurement to OEM coilers and gages. A disk with sample C code is included to assist in the implementation of the instrument. An optional National Instruments data acquisition card can also be included

The system is designed for use in CNC coilers and grinders, enabling the CNC designer to incorporate internal gaging without the necessity of designing gaging hardware or interfaces to external gages.

This manual contains information on the basic concepts of spring measurement, the included hardware and the included software.

## Spring Measurement Basics

Non-contact spring measurement is accomplished with a probe containing a non-contact sensor and an integral micrometer. The probe is mounted to the coiler face and positioned so the spring approaches the probe tip as it is formed (figure 1).

The probe uses an electric field to measure the gap between the probe tip and end of the spring. Changes in this gap create changes in output voltage, which correspond to changes in spring length.




Figure 1

## Calibration

To determine the corresponding spring length from the output voltage, the system must be calibrated with each use. During calibration, the user winds a spring but does not cut it off. The user then uses the system interface to teach it three measurement points. These three points are used in the calculation of spring length during production. The probe's micrometer is used to simulate changes in spring length by changing the probe's distance from the spring. During calibration the variables used in the length calculation are set. These variables are:

| Variable                                   | Example                |
|--|------------------------|
| Nominal length (desired length)            | 45mm                   |
| Tolerance                                  | $\pm 1$ mm             |
| Output voltage for nominal spring          | 0.065VDC (45mm spring) |
| Output voltage for nominal plus tolerance  | 4.56VDC (46mm spring)  |
| Output voltage for nominal minus tolerance | -3.84VDC (44mm spring) |

The relationship between the output voltage and the spring length is nonlinear. If actual length measurements are to be reported to the user, then the spring length calculation will have to include a linearization algorithm. The included software provides a function for doing this using a second order, three-point curve fitting algorithm (parabolic). If the voltage is only used to sort springs which exceed the tolerance, then linearization is not necessary.




Figure 2

Spring lengths are reported as deviation from nominal. For actual spring length, the nominal length will have to be added. Using our example values from above, the length function may return a length deviation of +0.02mm. The actual spring length would be 45.02mm.

### A typical calibration cycle:

1. Operator enters the nominal spring length
2. Operator enters the tolerance
3. Operator winds a spring but does not cut off
4. Operator sets the probe gap (see Important Considerations below)
5. Operator activates a “Teach” or “Set Nominal” button
6. System adjusts output voltage to near zero (or the operator is instructed to zero the output with the potentiometer)
7. System captures and stores the remaining offset voltage. This voltage represents a nominal spring
8. Operator uses the micrometer to adjust the probe position to simulate a spring at the “long” tolerance point.
9. System captures and stores the probe voltage for “long” tolerance
10. Operator uses the micrometer to adjust the probe position to simulate a spring at the “short” tolerance point.
11. System captures and stores the probe voltage for “short” tolerance
12. System uses stored spring length specifications and captured voltages to generate linearization coefficients (lp\_fit\_points).
13. Operator returns probe to nominal gap and starts production

### A typical measurement cycle

1. System coils a spring (no cutoff)
2. System reads probe voltage (an average of at least ten readings)
3. System calculates spring length and activates and sorting devices
4. System cuts off spring
5. System corrects for any length error.

## **Important Considerations**

### ***Sensitivity***

Probe sensitivity is defined as the rate of change of the output voltage for a given change in spring length. For example, a change of 5V for a 1mm change in length is *more sensitive* than a change of 1V for a 1mm change.

The probe sensitivity is dependent on the size of the gap between the probe tip and the spring. The smaller the gap, the greater the sensitivity.

***When calibrated, the output voltage range should be at least  $\pm 1V$  and not more than  $\pm 8V$ .***

If the probe is too sensitive (more than  $\pm 8V$  output change) then the probe must be moved further away from the spring and recalibrated.

If the probe is not sensitive enough (less than  $\pm 1V$  output change) then the probe must be moved closer to the spring and recalibrated.

These means that calibrations with smaller tolerances will have to be closer to the spring and larger tolerances may be farther away.

### ***Multiple Sampling***

To reduce the affect of any electrical noise in the system, probe voltage readings should be captured with multiple readings then averaged. For example, read and store ten readings of the probe voltage, sum the readings and divide by ten. The number of readings to be taken and averaged will depend on the running speed of the system and the amount of noise present in the signal.

### ***Thermal Stability***

The probe features a heating element that keeps the probe electronics at 130°F to prevent thermal drift. This circuit is controlled by a very low speed integrator. If power is interrupted to the probe, the probe will require two minutes to stabilize.

### ***Zeroing the Output Voltage (Offset)***

To provide a full voltage range during production, the output voltage for a nominal spring must be near zero. There are two ways to zero the output voltage:

- use a ten turn potentiometer accessible to the user (provided optionally)
- or use a zeroing voltage into pin 3 of J1.

When using the potentiometer, the zeroing voltage input (J1-3) is disabled. The potentiometer provides a stable reference for the driver.

When using the zeroing voltage input, the voltage must be stable and low in noise. The zeroing voltage is amplified (Gain  $\approx 50$ ), therefore any thermal drift or electrical noise can have a significant affect on the output voltage and the spring length measurement.

### ***Zeroing Errors***

If the probe is too close to the spring, the driver cannot be zeroed. The output voltage will remain positive. The probe must be moved farther away from the spring and re-zeroed.

If the probe is too far away from the spring, the driver cannot be zeroed. The output voltage will remain negative. The probe must be moved closer to the spring and re-zeroed.

### ***Probe Contact Errors***

Sometimes it is helpful to notify the operator if a spring makes contact with the probe tip. This may indicate a broken cutoff tool. The Test Voltage from J1-4 indicates this condition. Under normal operation conditions the voltage on this pin is less than 0.2VDC. If something contacts the tip, the Test Voltage will rise to over 0.7VDC. Using a routine to verify that this voltage is below 0.5VDC will monitor and report any probe contact errors.

## Hardware

### Probe Driver

The Capacitance Free Length Driver is a self contained system for driving the non-contact probe. The driver electronics produce an output voltage, which is proportional to the length of the spring at the probe. Longer springs (closer to the probe) produce more positive output voltages.

The output voltage offset must be adjusted to near zero for a nominal length spring. Probe Zero adjustments can be made by a DAC output voltage from the users data acquisition system or by a ten-turn potentiometer that can be purchased with the system.






Figure 3

The probe driver is mounted with two screws (M3-0.5). Do not loosen or remove the probe connector nut. See Figure 3 for panel cutout specifications. The maximum depth of the threaded mounting holes is 9.5mm (3/8 inch).



## Connections



| J1 Connections |     |                                    |  |
|----------------|-----|------------------------------------|--|
| Wire Colors    | Pin | Signal                             | Notes  |
| White          | 1   | Power In                           | +5 ± 0.5VDC, 0.7A max.   |
| Brown          | 2   | Probe Voltage Out                  | ±10VDC, proportional to spring length, more positive = longer.   |
| Black          | 3   | Zero Voltage In (Negative voltage) | 0 to -10VDC input voltage used to zero output voltage offset. 0.1V input change yields approximately 5V output change. |
| Blue           | 4   | Test Voltage Out                   | <0.5VDC normal operation, >0.5VDC when probe tip is grounded by contact with spring or other object.                   |
| Gray           | 5   | Ground (Common)                    |  |

## Software

The floppy disk supplied with the Capacitance Free Length Gage contains several examples of C language functions that may be useful in the implementation of the driver. None of these functions are required to use the driver. They are provided as tested implementation examples. They carry no warranty of functionality within any given system. They are ANSI C compatible and should be useable in most systems using a C development environment. All functions start with “lp\_” to identify them as Larson Procedures.

The following procedure list gives detail on the provided functions to ease the understanding and implementation of them.

---

### lp\_initialize

**Description** Initializes lp global variables. All variables are normally set to valid values during normal operation, however, this function is provided to prevent any unexpected errors after start up.

```
void lp_initialize( void )
{
    short_voltage    = -1.0;
    nominal_voltage  = 0.0;
    long_voltage     = 1.0;
    short_length     = -1.0;
    nominal_length   = 0.0;
    long_length      = 1.0;

    fit_points(short_voltage, nominal_voltage, long_voltage,
               short_length, nominal_length, long_length,
               &a_coeff, &b_coeff, &c_coeff    );
    find_horizontal_point(a_coeff, b_coeff, &horizontal_point);
}
```

---

### lp\_setup\_probe

**Description** Goes through the steps necessary to zero the probe and set up a linearization curve. These steps must be done every time the setup is changed. Much of this code must be written by the user because it involves taking input from the operator which can be done many different ways. This is simply a list of steps in the correct order.

**Return value:** none

**Parameters:** none

```
void lp_setup_probe()
{
```

```

/*
instruct user to put a nominal length spring in front of the probe
*/
    lp_zero_probe();

/*
obtain nominal spring length from user and store in nominal_length
*/
    nominal_length =

    nominal_voltage = lp_get_probe_voltage();

/*
instruct user to adjust the micrometer probe to simulate a long
(maximum) length spring
*/

/*
obtain long spring length from user and store in long_length
*/
    long_length =

    long_voltage = lp_get_probe_voltage();

/*
instruct user to adjust the micrometer probe to simulate a short
(minimum) length spring
*/

/*
obtain short spring length from user and store in short_length
*/
    short_length =

    short_voltage = lp_get_probe_voltage();

    if( -1 == lp_fit_points(
        short_voltage, nominal_voltage, long_voltage,
        short_length, nominal_length, long_length,
        &c_coeff, &b_coeff, &a_coeff)
        )
    {
        /* If there is a problem with the numbers input to fit_points,
code within these brackets will be run. */
    }

    if( lp_find_horizontal_point(a_coeff, b_coeff, &horizontal_point) )
    {
        /* If there is a problem with finding the horizontal point, code
within these brackets will be run. */
    }
}

```

---

## lp\_zero\_probe

**Description** This function will zero the output voltage of the probe driver by adjusting the zeroing voltage put out by a D to A converter. When using a potentiometer for zeroing, this function is substituted by instructions and feedback to the user to adjust the potentiometer.

**Return value:** If there is an error in acquiring the voltage, or the probe cannot be zeroed, a -1 is returned, otherwise the function will return 0;

**Parameters:** none

```
int lp_zero_probe()
{
/* 'i' is a counter to show how many times the loop has been executed
*/
    int i;

/* 'high' is the current upper limit of analog output voltage
The desired voltage should be less than this.
0 volts is the largest zeroing voltage you should put into the SPD-2 */
    double high = 0.0;

/* 'low' is the current lower limit of analog output voltage
The desired voltage should be higher than this.
-10 volts is the smallest zeroing voltage you should put into the SPD-2
*/
    double low = -10.0;

/* 'in' is the most recent voltage read */
    double in = 0.0;

/* 'last_in' is the previous voltage read */
    double last_in = 1.0;

/* 'out' is the voltage to be sent out to the probe driver */
    double out;

/* Three conditions must be met for the loop to continue:
    1. i < 100
    If the loop has executed 100 times, there's probably something
wrong.

    2. fabs(in-last_in) < 0.01
    Once the voltage read back from the probe driver stops changing,
you know that you've zeroed in on the appropriate output voltage.

    3. high > low
    If high becomes less than low you have reached the zero volts point
or something has gone wrong. */

for( i=0; i<100 && fabs(in-last_in)<0.01 && high>low; i++ )
{
/* Output a voltage halfway between the upper and lower limits. */
    out = (high + low)*0.5;
    lp_volts_out( out );
```

```

/* Update last_in and read new voltage. */
    last_in = in;
    in = lp_get_probe_voltage();

/* Check whether new voltage is positive or
negative and update high or low accordingly. */
    if( in > 0 )
        low = out;
    else
        high = out;
}

/* Check for errors */
if( i>=100 || fabs( in ) > 1.0)
    return -1;

return 0;
}

```

---

### **lp\_get\_spring\_length**

**Description** Reads the analog voltage from the probe and converts it to length.  
lp\_setup\_probe must be completed before this function is used.

**Return value:** Spring length

**Parameters:** none

```

double lp_get_spring_length()
{
    return lp_convert_volts_to_length( lp_get_probe_voltage() );
}

```

---

### **lp\_get\_probe\_voltage**

**Description** Acquires the output voltage from the spring probe. Range is  $\pm 10$ VDC.

**Return value:** Voltage reading.

**Parameters:**

```

double lp_get_probe_voltage()
{
    double voltage;

    /* put appropriate voltage reading code here */

    return voltage;
}

```

## lp\_volts\_out

**Description** Puts a new analog voltage on the D to A converter output. Range is 0 to -10VDC. This is used to zero the output voltage fo the driver.

**Return value:** voltage actually set

### Parameters:

```
double lp_volts_out( double voltage )
{
    if( voltage > 0.0 )
        voltage = 0.0;
    else if( voltage < -10.0 )
        voltage = -10.0;

    /* put appropriate voltage output code here */

    return voltage;
}
```

---

## lp\_convert\_volts\_to\_length

**Description** Converts a voltage to its associated length based on the specifications set in lp\_setup\_probe. This function is called from within lp\_get\_spring\_length.

**Return Value:** Spring length.

### Parameters:

**voltage** The voltage to be converted to a length

```
double lp_convert_volts_to_length( double volts )
{
    /* Check to see if the aforementioned horizontal point has been reached
    or exceeded. */
    if( (nominal_voltage == horizontal_point) ||
        (nominal_voltage > horizontal_point && volts <=
horizontal_point) ||
        (nominal_voltage < horizontal_point && volts >=
horizontal_point) )
        return a_coeff*horizontal_point*horizontal_point +
b_coeff*horizontal_point + c_coeff;

    /* This point in the program should be reached under normal operating
    conditions. */
    return a_coeff*volts*volts + b_coeff*volts + c_coeff;
}
```

---

## lp\_fit\_points

**Description** Calculates the coefficients of a quadratic curve that fits the three points given.

**Return value:** If the values sent are invalid a -1 is returned, otherwise the function will return 0;

### Parameters:

**V1, V2, V3** Doubles. The measured probe output voltage at the short, nominal, and long spring lengths.

**L1, L2, L3** Doubles. Short, nominal, and long spring lengths. Be sure they are in the same order as the voltages.

**a, b, c** Double pointers. The three quadratic coefficients that determine the curve that fits the three points: (V1, L1) (V2, L2) (V3, L3).

$$\text{Length} = a * \text{Voltage} * \text{Voltage} + b * \text{Voltage} + c$$

```
int lp_fit_points(double V1, double V2, double V3,
                 double L1, double L2, double L3,
                 double *a, double *b, double *c )
{
    int i;
    double R1[4], R2[4], R3[4], divider;

    R1[0] = 3;
    R1[1] = V1 + V2 + V3;
    R1[2] = V1*V1 + V2*V2 + V3*V3;
    R1[3] = L1 + L2 + L3;

    R2[0] = V1 + V2 + V3;
    R2[1] = V1*V1 + V2*V2 + V3*V3;
    R2[2] = V1*V1*V1 + V2*V2*V2 + V3*V3*V3;
    R2[3] = L1*V1 + L2*V2 + L3*V3;

    R3[0] = V1*V1 + V2*V2 + V3*V3;
    R3[1] = V1*V1*V1 + V2*V2*V2 + V3*V3*V3;
    R3[2] = V1*V1*V1*V1 + V2*V2*V2*V2 + V3*V3*V3*V3;
    R3[3] = L1*V1*V1 + L2*V2*V2 + L3*V3*V3;

    divider = R1[0];
    for( i=0; i<4; i++ ) R1[i] = R1[i] / divider;
    divider = R2[0];
    for( i=0; i<4; i++ ) R2[i] = R2[i] - (divider * R1[i]);
    divider = R2[1];
    if( divider == 0 )
        return -1;
    for( i=0; i<4; i++ ) R2[i] = R2[i] / divider;
    divider = R3[0];
    for( i=0; i<4; i++ ) R3[i] = R3[i] - (divider * R1[i]);
    divider = R3[1];
    for( i=0; i<4; i++ ) R3[i] = R3[i] - (divider * R2[i]);
    divider = R3[2];
    if( divider == 0 )
        return -1;
```

```

for( i=0; i<4; i++ ) R3[i] = R3[i] / divider;

*a = R3[3];
*b = R2[3] - R2[2] * R3[3];
*c = R1[3] - R1[2] * R3[3] - R1[1] * ( R2[3] - R2[2] * R3[3] );

return 0;
}

```

---

### **lp\_find\_horizontal\_point**

**Description** Finds the horizontal point. It uses the a, b, c coefficients calculated above and its output is used in the convert\_volts\_to\_length function.

The derivative (with respect to x) of  $[a*x*x + b*x + c]$  is  $[2*a*x + b]$

To find the horizontal (zero slope) point you must solve for x when  $[2*a*x + b == 0]$

This comes out to be  $[x = -b/(2*a)]$

**Return value:** If the values sent are invalid ( i.e. tolerance > nominal ) a -1 is returned, otherwise the function will return 0;

**Parameters:**

**nominal** Float. The nominal, desired length for the spring to be measured.

**tolerance** Float. The tolerance for the springs being measured. This determines the point at which springs are sorted and the point at which the probe will setup.

```

int lp_find_horizontal_point(double a, double b, double *x)
{
    if( a == 0.0 )
        return -1;

    *x = b/(-2.0*a);
    return 0;
}


```

---

**Gaging System**  
**TWO YEAR WARRANTY**

The Larson Systems Inc. Gaging System parts and labor are warranted against defects in material and workmanship to the consumer for a period of twenty four months from the date of purchase. The foregoing warranty is exclusive and in lieu of all other warranties whether written, oral, or implied (including any warranty of fitness for purpose). This warranty covers all parts, except consumable items. It applies only to gages and accessories which have been installed and operated in accordance with instructions in our reference manuals, have not been tampered with in any way, misused, suffered damage through accident, neglect or conditions beyond our control and have been serviced only by authorized personnel. Larson Systems Incorporated is not responsible for loss in operating performance due to environmental conditions, such as humidity, dust, corrosive chemicals, deposition of oil or other foreign matter, spillage or other conditions beyond our control. There are no other warranties expressed or implied, and Larson Systems Incorporated shall not be liable under any circumstances for incidental or consequential damage. If it appears within two years from the date of shipment by Larson Systems Inc. that the equipment as delivered does not meet the warranties specified above and the Purchaser so notifies the Larson Systems Inc. promptly, Larson Systems Inc. at its Mpls MN facility, shall correct any defect, including non-conformance with the specifications, at it's option, either by repairing any defective part(s), or by making available a replacement or required part.

Warranty service is conducted at LSI's facilities in Minneapolis, MN. Return the tester freight prepaid during the warranty period, and Larson Systems Incorporated will make a warranty determination, repair and return the tester freight collect. Shipments sent collect will be rejected. The foregoing shall constitute the sole remedy of the Purchaser and the sole liability of Larson Systems Inc.



**Larson Systems Inc.**  
10073 Baltimore Street NE  
Minneapolis, MN 55449-4425  
[www.larsonsystems.com](http://www.larsonsystems.com)

763-780-2131  
1-877-780-2131  
Fax: 763-780-2182  
[info@larsonsystems.com](mailto:info@larsonsystems.com)



060-1000-0075-00A